

L208008

29-06-23 REV.02

LeoVince®

leovince.com



International Customer Service:
info@leovince.com

North America Customer Service:
infousa@leovince.com - +1-844-536-7625

LeoVince®

ART 208008R LAMBDA WIRE EXTENSION HARNESS





FOR YAMAHA TÉNÉRÉ 700 EURO 5

TYPE: DM11; A/01, A/03, A/07, A/09, A/11 -
DM15; A/01, A/03 - DM16; A/01, A/03


FITMENT NOTICE FOR NON-EUROPEAN COUNTRIES:


Wire extension harness is required only if your O2 sensor is near the exhaust ports on motor.



NOTE / NOTES / REMARQUES /
ANMERKUNGEN / NOTAS

NOTE / NOTES / REMARQUES /
ANMERKUNGEN / NOTAS





NOTE / NOTES / REMARQUES /
ANMERKUNGEN / NOTAS