





BF30_BF30K



CBR1000 (2017)



Rimuovere le viti originali
Remove the original screws
Enlevez les vis originales
Entfernen Sie die Originalschrauben
Mover los tornillos originales



BF30_BF30K

CB650F (2017)

CB500F (2019)

